

Modular Firmware

V2.2.56_220713 Release Note

(2022-07-13)

Device Model	DS-KD8003-IME1、DS-KD8003-IME2
Firmware Version	V2.2.56_220713
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

FIX

1. Supports CS registration mode in private SIP registration. Enable clients to initiate register once to the server to finish the registration. Filling the main station IP (main door station IP) to the main door station IP (door extension IP).
2. Supports switching language without device rebooting.
3. Fixed the problem that the actual lock time is more than the set duration of 1 second.

Modular Firmware


V2.2.56_220607 Release Note

(2022-06-20)

Device Model	DS-KD8003-IME1、DS-KD8003-IME2
Firmware Version	V2.2.56_220607
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

New

- Compatible with the Touching Modules:
 - DS-KD-TD version: V1.0.1_220607
 - DS-KD-TDM version: V1.0.1_220607
 - DS-KD-TDE version: V1.0.1_220607
- Support advertisement publishing.



Fix

- The card compatibility was optimized from 10000 to 6000.
- All the user information will be listed when searching by "%".

Modular Firmware

V2.2.52_220518 Release Note

(2022-05-30)

Device Model	DS-KD8003-IME1、DS-KD8003-IME2
Firmware Version	V2.2.52_220518
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

Fix

- Compatible with the new version Indoor Stations:
 - DS-KH9310-WTE1(B)
 - DS-KH9510-WTE1(B)
 - DS-KH6350-WTE1
 - DS-KH6350-TE1
 - DS-KH6320-LE1(B)
 - DS-KH6320-LE1(B)/White
 - DS-KH6320-TE1(B)
 - DS-KH6320-WTE1(B)
 - DS-KH6360-TE1
- Compatible with more card reader models:
 - DS-K1108AD
- Fix the problem that standard SIP cannot be automatically registered after restarting.

Modular Firmware

V2.2.52_211126 Release Note

(2021-11-28)

Device Model	DS-KD8003-IME1、DS-KD8003-IME2
Firmware Version	Modular Door Station: V2.2.52_211126
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

Fix

- Fixed some bugs.

Modular Firmware

V2.2.50_210728 Release Note


(2021-07-15)

Device Model	DS-KD8003-IME1、DS-KD8003-IME2
Firmware Version	Modular Door Station: V2.2.50_210728
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

Modify

1、 Since V2.2.50_210728, remote degradation of devices is not supported in all subsequent versions. When degradation occurs, it will prompt Upgrading failed.

Notice: Although the device can be degraded by serial port, the device will fail to start and cannot change the version by using serial port again, which means that the device will be completely unusable.



2、 Newly support for French voice prompt "calling", "the line is busy" and "the door is open"
3、 The method of adding sub door station is changed to the same method as protocol 1.0. (Fill in the Main Door Station IP and Registration Password in the configuration interface of Sub Door Station)

Local System Network Video/Audio Image Event Schedule Intercom Access Control User

Device No. Session Settings Time Parameters Ringbacktone Settings Press Button to Call I/O Settings

Sub Module Configuration Number Settings

Device Type

Floor No.

Door Station No.

Advanced Settings

Save

Local System Network Video/Audio Image Event Schedule Intercom Access Control User

Device No. **Session Settings** Time Parameters Ringbacktone Settings Press Button to Call I/O Settings

Sub Module Configuration Number Settings

Registration Password

Main Door Station IP

Main Station IP

Center IP

Save

Note: you can refer to the attached file below about how to add a Sub door station.



How to add a single sub door station

Modular Firmware

V2.2.13_210129 Release Note

(2021-02-07)

Device Model	DS-KD8003-IME1、DS-KD8003-IME2
Firmware Version	Modular Door Station: V2.2.13_210129
iVMS-4200 Version	Latest version
Hik-Connect APP	Latest version

Modify

1. Optimize RS485 communication efficiency with sub-module

Modular Firmware


V2.2.13_201222 Release Note

(2021-01-05)


Device Model	DS-KD8003-IME1、DS-KD8003-IME2
Firmware Version	Modular Door Station: V2.2.13_201222
iVMS-4200 Version	3..5.x.x Build21xxxx
Hik-Connect APP	4..11.0.927220

New Function

1. New refresh button is used to refresh the status of added devices



2. Added 'All' option, indoor station and sub-door station will be displayed together.



Modify

1. Modify the language display of some errors

